

## Brúsky a leštičky

### Priemery upevnenia pre adaptéry GLOB ALU

Producent	Typ brúsky	(min-1)	Priemer upevnenia adaptéra	Typ adaptéra ALU
Bosch	PWS 8-125 CE	2800 - 11000	42mm	ALU-01-42 ALU-04-42
	GWS 750 S			
	GWS 850 CE			
	GWS 7-115 E			
	GWS 9-125S			
	GWS 17-125 CIE GWS 15-125 CIE/X/H/P GWS 14-125 CIE GWS 13-125 CIE GWS 12-125 CIE	2800 - 11500	50mm	ALU-01-50 ALU-04-50
	GWS 15-125 CIT/H	2800 - 9300		
GWS 15 -125 Inox GWS 17-125 Inox	2200 - 7500			
LUX	WS-125	3000 - 11000	42mm	ALU-01-42 ALU-04-42
Redstone	RS 1050-125MA	3000 - 11000		
Graphite	59G186	3000-11000		
AEG	WS 12-125 XE	2800 - 11000		
	WS 13-125 SXE	2800 - 11500		
Sparky	M 750E HD	3000 - 10000		
	PMB 1200 CE (180)	600 - 2800		
Mac Allister	MSSP1200 (180)	900 - 3300		
	MEAG 900	3000 - 11000		
Metabo	WEV 15-125 Quick	2800 - 11000		
	WEV 15-125 Quick Inox	2000 - 7600		
	WEV 17-125 Quick	2800 - 11000		

	WE 14-125 Plus	3000-11500		
	WE 9-125 Quick	3000 - 10000		
	WEV 10-125 Quick	2800 - 10500		
	WEV 11-125 Quick	3000-11500		
	WE 14-125 VS	2800-10500		
Milwaukee	AGV 15-125XE	2900 - 11000	42mm	ALU-01-42 ALU-04-42
AEG	WS 12-125XE	2800-11000	42mm	ALU-01-42 ALU-04-42
	WS 13-125SXE	2800-11500		

Dewalt	D28136-QS	2800-10000	44mm	ALU-01-44 ALU-04-44
	DWE4257 - nowa	2800-10000		
Dewalt	DWE4257 (1500W)	2800-10500		
	DWE4357 (1700W)	2200-10500		
	DWE4369 (1700W)	1800-8000		
	DWE4377 (1700W)	2200-10500		
Sparky	M750E	2800-10000	42mm	ALU-01-42 ALU-04-42
DWT	WS 10-125 TV	2800-11000	42mm	ALU-01-42 ALU-04-42
Makita	SA5040C	2000-7800	42mm	ALU-01-42 ALU-04-42
	9565CVR	2800-12000		
	GA5040C	2800-11000		
Hitachi/ Hi koki	G13 SE2 G13 SE4 G13 VA		42mm	
YATO	YT82101	3000-12000	50mm	ALU-01-50 ALU-04-50